

Forced 7161 S. Peoria 18E, Englewood, Co 80112
Aeromotive (720) 348 -0622 FAX (303) 799-6443
Technologies FAA-PMA forcedaeromotive.com

SERVICE BULLETIN 0624-001
6-24-16, Revision IR

RECOMMENED OVERHAUL PERIOD-SUPERCHARGER

Background:

The previous recommend overhaul period for Cessna 182 superchargers installed under STC SA10232SC was 1400 hours. Recommended overhaul period is now 2000 hours.

Eligibility:

FAT supercharger systems, STC SA10232SC, serial numbers 0001 and on using superchargers part numbers 182LRVSCC-10 and 182LRVSCC-30.

Contact FAT for technical assistance.

END